



SUBLIFLOK 1602



SPECIFICATIONS

APPLICATION

1. Printing and cutting

- Prepare the image on positive following the instruction of the printer manufacturer:
- Take care of the printing and drying temperatures
- Use the adequate printing profile
- Remove the flock from the printer.

2. Heat pressing

- Weed the excess material and remove the paper carrier.
- Position and heat press the logo onto the garment protected by a silicone paper at 170°C during 50 seconds.
- For sensitive garments:
 - 1/ Heat press the logo at 170°-50s with the carrier
 - 2/ Remove the carrier and heat press the logo on the garment at 160°C during 20 seconds.

FIBRES
THICKNESS:



White polyester flock media (velvet touch)
0.50 mm
For sublimated printers for heat transfer applications

CARRIER: Paper



APPLIES ON

Cotton ● Polyester ● Acrylic and similar fibres.

CARE & MAINTENANCE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only
- Printable media are very sensitive: always handle with care and preferably with gloves.
- Always store the roll in a plastic bag protected from dust.
- It is important always using official inks from the printer manufacturer.

WASH

- Max 60°C
- Preferably inside out
- Do not bleach
- Tumble-dry approved
- Dry-cleaning unapproved

STORE

- Up to 1 year
- In a dry room (15-25°C)
- Away from sunlight
- In vertical position

Chemica
Heat transfers for textiles

NOTE: For best results, it is recommended to TEST prior to starting standard production