





145°C



PEEL: HOT







SPECIFICATIONS

APPLICATION

1. Printing and cutting

- Prepare the image on positive following the instruction of the printer manufacturer:
- -Take care of the printing (45°C) and drying temperatures (50°C).
- Use the adequate printing profile (for instance, with Roland, select Colorip or Versawork, and then profile TTRH, textile).
- Remove the flex from the printer and wait for the complete drying of inks at room temperature, at least 4 hours.

2. Heat pressing

- Weed the excess material.
- Using an application tape is not compulsory to transfer the image. It is possible to transfer the image by hand or with a clear polyester application tape. Do not use a paper application tape
- Position and heat press on a SEFA machine the image on the garment protected by a silicone paper at 145°C–15seconds medium pressure.
- If you use it, peel the application tape off when hot.

THICKNESS:



Metallic polyurethane media 85 microns

CARRIER: Clear polyester



APPLIES ON

Cotton • Polyester • Acrylic and similar fibres.

CARE & MAINTENANCE

- --- Always respect the garment's instructions
- → Allow 24 hours after application before washing
- Iron the backside only
- Printable media are very sensitive: always handle with care and preferably with gloves.
- Always store the roll in a plastic bag protected from dust.
- It is important always using official inks from the printer manufacturer.

WASH

- Cold hand-washing only
- Preferably inside out
- Do not bleach
- Tumble-dry unapproved
- Dry-cleaning unapproved

STORE

- Up to 1 year
- In a dry room (15-25°C)
- Away from sunlight
- In vertical position

